The Hendry-Davis Farmstead is centered on a two-story frame dwelling built about 1875 with a five-bay main elevation and a cross gable, segmental arched windows and doorway, and a two-story rear wing with a two-story open porch. Outbuildings include a frame summer kitchen, a frame meat house, a garage, a bank barn, a second frame barn, a wagon shed/granary, a hog barn, and a chicken house, all dating from the period about 1900-1920. The interior of the house has grained woodwork of a high level of craftsmanship. The farm was established about 1865 by Charles Hendry (1798-1877), one of several properties owned by him on the tract "William and Elizabeth", which had been inherited by his wife Eleanor Burgee Hendry. In 1874, Richard Davis (1829-1906) bought the farm of 141 acres and probably built the present house. The agricultural outbuildings mostly date from the period 1901-1920 when the farm was owned by Vernon T. Watkins (1872-1943). The farmstead is moderately significant for the architecture of the dwelling, a largely unaltered example of the late 19th century vernacular house with influences of the Renaissance and Italianate Revivals, and the high quality of craftsmanship in the grained interior The agricultural outbuildings are also moderately significant for woodwork. the number and variety of surviving buildings of the first quarter of the 20th century.

F-7-99 Hendry-Davis Farmstead Urbana Frederick County

### HISTORIC CONTEXT:

# MARYLAND COMPREHENSIVE HISTORIC PRESERVATION PLAN DATA

Geographic Organization: Piedmont (Harford, Baltimore, Carroll, Frederick, Howard, Montgomery Counties, and Baltimore City)

Chronological/Development Period:
Agricultural-Industrial Transition, A.D. 1815-1870
Industrial/Urban Dominance, A.D. 1870-1930

Prehistoric/Historic Period Themes: Architecture, Landscape Architecture and Community Planning

# Resource Types:

Category: Building

Historic Environment: Rural

Historic Function and Use:

Domestic/single dwelling/residence
Domestic/secondary structure/kitchen
Domestic/secondary structure/other dependencies
Agriculture/subsistence/animal facility/barn
Agriculture/subsistence/storage/granary
Agriculture/subsistence/agricultural outbuilding

Known Design Source: None

# Survey No. F-7-99

# Maryland Historical Trust State Historic Sites Inventory Form

Magi No.

DOE \_\_yes \_x no

	<u> </u>			
1. Nan	<b>ne</b> (indicate pr	referred name)		
historic He	ndry-Davis Farmstea	ď		
and/or common	1			
2. Loc	ation		· · · · · · · · · · · · · · · · · · ·	
street & numbe		ctillory Pood		
·			<del>-</del>	not for publication
city, town U	rbana	_x_ vicinity of	congressional district	6th
	aryland	county	Frederick	
3. Clas	ssification	· · · · · · · · · · · · · · · · · · ·		
Category district building(s) structure site object	Ownership public private both Public Acquisition in process being considered not_applicable	Status  X occupied  unoccupied  work in progress  Accessible X yes: restricted yes: unrestricted no	Present Use agriculture commercial educational entertainment government industrial military	museum park X private residence religious scientific transportation other:
4. Owi	ner of Prope	erty (give names a	nd mailing addresse	s of <u>all</u> owners)
name <sup>M</sup>	ehrle W. & Mildred	J. Murphy		
street & numbe	, 3437 Price's Di	stillery Road	telephone n	0.:
city, town	jamsville	state	and zip code MD	21754
5. Loc	ation of Leg	al Description	on	
courthouse, reg	gistry of deeds, etc. Fr	ederick County Court	house	liber 632
street & numbe	r 100 W. Patrick S	treet		folio 118
city, town	Frederick		state	MD 21701
6. Rep	resentation	in Existing	Historical Surv	eys
title				
date			federal stat	e county local
epository for s	survey records			
city, town			state	

# 7. Description

Survey No. F-7-99

Condition     Check one     Check one       excellent     deteriorated     unaltered     original site       good     ruins     altered     moved date of move       fair     unexposed	
---	--

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

#### CONTRIBUTING RESOURCE COUNT: 9

The Hendry-Davis Farmstead is centered on a two-story frame dwelling built about 1875 and its associated domestic and agricultural outbuildings, including a frame summer kitchen and a meat house of about the same date and a bank barn of about 1900, a wagon shed/granary, a hog barn, a chicken house, and a garage, all of about The farmstead is located on the east side of Price's Distillery Road about one mile south of Fingerboard Road (Md. 80) near Urbana, Frederick County, The farmstead is located on a hilltop at the end of a driveway running Maryland. east from Price's Distillery Road past a non-contributing modern residence on a parcel subdivided from the original farm property. The principal elevation of the house faces northwest. The domestic outbuildings are located east and south of the house, except the garage, which is located north of the house, and the agricultural outbuildings are grouped south and southwest of the domestic buildings. Dates of the structures are based on land records, architectural evidence, and a biographical sketch of Vernon T. Watkins, the owner of the farm from 1902 to 1920, in Williams & McKinsey's <u>History of Frederick County</u> (1910).

The dwelling has a five-bay main elevation with a cross gable and a one-story A two-story rear wing extends from the northeast corner of the house and has a two-level open porch on the west side. The exterior is covered with german sidir and the roof is standing seam metal. An interior end chimney is on the east gable end and a probable matching chimney on the west gable has been replaced by an exterior brick chimney in the mid-20th century. The window and door openings on the northwest elevation have segmental arches and the windows have louvred shutters in a The sash is 1/1 on the main elevation. The doorway has a matching profile. two-light transom and narrow sidelights. The door is a four-panel type. The center cross gable has a round-arched 1/1 window. The porch has simple brackets and pendants with chamfered posts. The pilasters at the wall junction of the porch have a molded paneled base, indicating that the porch posts are replacements of the original supports. The wood deck remains in place. The east and west gable ends have a single bay with 1/1 sash on the first story and 2/2 on the second. In the side gables and the rear wing the window and door openings have flat arches and The two-level porch of the wing is integral to the structure and louvred shutters. has a plain balustrade railing on the second story level. The doorways on both levels have two-light transoms and four-panel doors. The south end of the wing has a single arched 2/2 attic window and an interior chimney.

The interior of the house has a central hall plan with a single room on each side. The most striking feature of the interior trim is the finely grained woodwork of the door and window surrounds. The doors from the hall to the side parlors have two-toned finishes resembling oak on the pine surfaces. In the second story west room, a corner closet and an adjoining door are both finished in a lighter color grained to resemble maple. A simple pediment with an applied medallion finishes the top of the closet.

Period prehistor	archeology-historic agriculture agriculture architecture art	• •	military music	religion science sculpture social/ humanitarian theater ntransportation
Specific dat	es C. 1865-1875; 1902-19	Builder/Architect		
check: Ap	plicable Criteria: _A and/or plicable Exception: _A	BxCD ABCDI	EFG × local	

Survey No.

F-7-99

8. Significance

Prepare both a summary paragraph of significance and a general statement of history and support.

The Hendry-Davis Farmstead is moderately significant in architecture for the largely unaltered exterior of the dwelling and for the mostly intact finely grained interior wood trim. The house is a good example of the vernacular dwelling of the last quarter of the 19th century, displaying in its five-bay elevation the segmental arches, cross gable, round-arched gable windows, and bracketed porch the influences of the Renaissance and Italianate Revivals and the basic form of a German-influenced rural dwelling in its plan of a main section and perpendicular rear wing. The grained interior trim is in excellent condition and shows the work of a skilled craftsman of the late 19th century, as yet unidentified. The farmstead is also derately significant for the number and variety of surviving outbuildings of both ucmestic and agricultural use. Among bank barns in the Urbana Region, the Hendry-Davis barn is among the less common for its not having been altered for dairy The farm was established about 1865-1875 by Charles Hendry (1798-1877), whose wife Eleanor had received the tract "William and Elizabeth" from her mother Jane The farm appears on the 1873 Titus Atlas map as one of several Burgee in 1864. properties on this large tract owned by Charles Hendry. In 1874, Richard Davis (1829-1906) purchased about 141 acres of the tract for \$2,100. The architectural features and finish of the house strongly suggest that it was built during Davis' Mrs. Murphy, the current owner, recalls that a deteriorated log dwelling was formerly located down the hill to the south of the present farmstead. This may have been the house indicated on the 1873 map. The Davises sold the farm in 1896 and, after several interim owners, Vernon T. Watkins (1871-1943) bought the farm in According to his biography in the 1910 History of Frederick County, he made 1902. Most of the agricultural outbuildings were several improvements to the place. probably built during his 18-year ownership.

<u>9. Ma</u>	jor Bibliographica	I References su	rvey No. F-7-99
Land Recor	, Jacob M. <u>Names In Stone</u> , V.l rds of Frederick County O. Atlas of Frederick County, T.J.C., and Folger McKinsey.		1910. Reprint
Balt.imo	re: Regional Publishing Co , 1	979 <sub>p</sub> 723	
<u> 10. G</u>	eographical Data		·
Acreage of no Quadrangle r UTM Reference		Quadrangle	scale 1:2400 <u>0</u>
<b>^</b>	do NOT complete UTM references  String Northing	B L L L L L L	Inthing
C		P	
Verbal boun	idary description and justification		
Approximat	tely 10 acres centered on the	dwelling on Tax Map 97, Parcel	. 225.
List all state	es and counties for properties overla code	apping state or county boundaries	code
state	code	county	code
11. F	orm Prepared By		
name/titie	Janet L. Davis, Historic Site	s Surveyor	
organization	Frederick County Planning &	Zoning Dept. date January 199	94
street & numb	er 12 E. Church Street	telephone 696-2958	}
city or town	Frederick	state MD 21701	
	an Act of the Maryland Legist Code of Maryland, Article 41.  The survey and inventory are	Inventory was officially createlature to be found in the Anno, Section 181 KA, 1974 supplementally being prepared for information not constitute any infringemen	tated ent. n and
	return to: Maryland Histor	rical Trust	

21 State Circle
Annapolis, Maryland 21401
(301) 269-2438

CROW.

PS-2746

# 7.1 Description (Continued)

### Domestic outbuildings:

Summer kitchen: The small frame summer kitchen is located immediately east of the rear wing. It has german siding and a corrugated metal roof. On the south elevation is an off-center replacement door. No other openings in the exterior are visible except for a small arched opening on the west gable end, which is boarded. Although no evidence of a chimney is apparent on the exterior, Mrs. Mildred Murphy, the current owner, said the building has only been used as a summer kitchen and currently as a storage building. It probably dates from the late 1890's.

Meat house: The frame meat house is just southeast of the rear wing of the house. It has a two-level height, incorporating a small loft above the meat storage room on the first level. The exterior is covered with board and batten siding and the roof is corrugated metal. Two doors are on the west gable end, one on each level. The meat house probably also dates from the 1890's, but could be as early as the 1870's.

Garage: The small frame garage located north of the house was probably built in the period 1900-1920. It has vertical siding and an open side on the south gable end. The roof is corrugated metal.

# Agricultural outbuildings:

Bank barn: The frame bank barn was probably built about 1900. It has tongue-and-groove siding and a corrugated metal roof. The south elevation has adjoining loafing sheds added from the 1940's to the 1970's. The stall level of the barn has not been altered for milking parlor use, as is more common among bank barns of the early 20th century. Mrs. Murphy confirmed that the farm has raised beef cattle since the early 1900's and a few dairy cows were only kept for domestic use. A non-contributing concrete silo stands next to the ramp on the north elevation.

Frame barn: A second frame barn is located just west of, and at a slight angle to, the bank barn. It is a rectangular building with sliding doors on the north side. Its date is unknown, but its weathered vertical siding and mortise and tenon construction suggest that it was built in the early 20th century. It has a corrugated metal roof and an open shed on the south side added in the 1940's.

Wagon shed/granary: The wagon shed is located north of the bank barn. Built about 1900, it was constructed to store both corn and wheat. The north side crib has flush tongue-and-groove siding to store wheat, and the south side crib has vented vertical boards in which corn was stored. The gable end surfaces are also covered with tongue-and-groove. The roof is corrugated metal. According to Mrs. Murphy, by the 1950's, both cribs were used for corn storage.

Chicken house: The rectangular frame chicken house is located just north of the wagon shed. It has board and batten siding and a corrugated metal roof. The vertical board door in the west elevation is flanked by 3/3 windows, with a

Survey No. F-7-99


# 7.2 Description (Continued)

vertical pair of windows on the south side. The chicken house was built in the early 20th century.

Hog barn: The deteriorated frame hog barn is located northwest of the frame barn. It appears to have been built about 1920. The siding is board and batten and the shed roof is corrugated metal. On the west elevation, the low doors and surrounding siding are greatly deteriorated and patched with sections of plywood and corrugated metal. The floor of the barn is revealed on this side as a poured concrete slab.

Lot Size, Description	n,
Original Tracts,	
Miscellaneous	

Liber/Folio Grantee Grantor Cost 1709/44 Mildely in Davidkm \$200,000 13 Mong 91 muching & Rolein Chery Mushly 632/118 part of "William and Elizabeth" 138 a. IR., 35 p. - 12 a. mehrle M. + Charles E. + 26 gan 60 Mamie C. Musky milared . Murphy conveyance of 137a, 32, 35 p. 433/464 Wallas W. Sz Charles & Mary M. 16/Mar 42 4 Mannie Musky rehne 331/67 Wallas W. + Nermon J. 4 Edith P. Zula a. 29 Mar 20 Waltens Kehne PHH 13/144 1379., 3R, 35 for Vernon J. Reifies Harman #4600 Magreeder Wathens 17 goin 02 DHH 13/144 Rufus . Edward Hanne TG 4/438, 119px 1874 \$3 800 Magreeder 17gano 2 V. Rechols DHH 11/539 Edward Nichola William + \$4215 28 aug-01 Ellen M. Sauther JLJ 14/137 William Smither 29 apr 1896 Cenn C. Davis \$4000 14/ a., 2R. 35 p. less 3/49. oneyed Pichardhauis Charles & Eleanor Hendry 164/438 part of "William and Elizabeth 141 a., 2R., 35 fo. #2100 11 apr 1874 JWLC 1/622 Ellen Hendry entire tract of "William and Elizabeth" Jane Burger Singleton Burge ackam Borps 21 May 1861








Fig. 1-79

Hewary- Cau Canterna

Therena Round

Photo: Jane = 1 and

Photo: Jane = 1 and

North

1/5



1 == 360 Promoter Parity Fhoto Thee " Cour 189- 188 " B 4 " 1 2 Train to 12 "



Mark the state of Grower door first floor and From

7.7



New York Hit Plant Land Cold



- Eng- 10 Louis Farmal and Thederick Communication No beautiful office to the Committe Filoren mana Meat hours with there



Neg. 100, 1/1/2, SHTO CHOLONOV . WIN



Mineral La Properties And Section 2011 FARE THE FEW HOLFIN

1 77



1 100